

HAZARDOUS WASTE PROGRAM D. DEPT. OF NATURAL RESCURO

MAR 0 4 2002

Solutia Inc.

. F. Queeny Plant

. 201 Russell Bivd.

St. Louis, Missouri 63104 Tel 314-622-1400

Certified Mail—Return Receipt Requested

March 1, 2002

Missouri Department of Natural Resources Hazardous Waste Program P.O. Box 176 Jefferson City, Missouri 65102

Attn: Mr. John Beard

Dear Mr. Beard:

Pursuant to 40 CFR 262.41, 40 CFR 262.75 and 40 CFR 265.75, enclosed herewith please find the 2001 Biennial Hazardous Waste Report for the Solutia Inc., John F. Queeny Plant.

If there are any questions or the need for additional information, please contact Mr. Richard B. Hampel, ESH Coordinator, at (314) 622-1455.

Sincerely,

Robin K. Prokop Plant Manager

Enclosures:

BO MAY

130 MAY 2002 RAFQCH LYC/TRI-COR

RO0407291 RCRA RECORDS CENTER

11 APR 2002

OMB#: 2050-0175 Expires 12/31/2003 RECEIVED MAIL THE COMPLETED FORM United States Environmental Protection Agency TO: MAR 0 4 2002 RCRA SUBTITLE C SITE IDENTIFICATION FORM The Appropriate EPA Regional or State Office. HAZARUUUS WASTE PROGRAM NO DEPT OF NATURAL RESOURCES 1. Reason for Submittal A. Reason for Submittal: and Status of Information To provide initial notification (to obtain an EPA ID Number for hazardous waste, universal waste, or used oil Supplied (see instructions activities). on pages 10 and 11) To provide subsequent notification (to update site identification information). CHECK CORRECT BOX(ES) As a component of a First RCRA Hazardous Waste Part A Permit Application. As a component of a Revised RCRA Hazardous Waste Part A Permit Application (Amendment # ____ X As a component of the Hazardous Waste Report. B. Status of Information Supplied: Updated site information 2. Site EPA ID Number **EPA ID Number:** (see instructions on MOD004954111 page 11) 3. Site Name (see Legal Name: instructions on page 11) Solutia Inc., John F. Queeny Plant 4. Site Location Street Address: 201 Russell Boulevard Information (see State: Missouri instructions on page 11) City, Town, or Village: St. Louis County Name: St. Loui 5. Site Land Type (see Site Land Type: X Private instructions on page 11) 6. North American A. 325199 T2 **Industry Classification** System (NAICS) Code(s) for the Site (see c. 325199 U instructions on page 11) 7. Site Mailing Address Street or P. O. Box: Same (see instructions on page 12) City, Town, or Village: State: County:

County Name: St. Louis City			
strict Federa	al Indian Municipal State Other		
B . 3241	91 03		
D.			
	Zip Code:		
MI: B.	Last Name: Hampel		
	Phone Number Extension:		
Inc.	Date Became Owner (mm/dd/yyyy):		
t Federal	☐ Indian ☐ Municipal ☐ State ☐ Other		
	Date Became Operator (mm/dd/yyyy):		
trict Federa	I Indian Municipal State Other		
<u> 1</u>	Same as Page 1 of EPA Form 8700-12 Same as Page 1 of EPA Form 8700-23		
	B. 3241: D. MI: B.		

8. Site Contact Person

(see instructions on

9. Legal Owner and

Operator of the Site (see instructions on

pages 12 and 13)

page 12)

							ONAD#: 2050 013	75 Expires 12/31/200
_			J 			- 1, 1——	EPA ID No.	5 Expires 12/5/1/200
10.	Type of Regu	lated Waste Activi	ty (Mark 'X' in the a	appropriate bo	xes. See ir	structions	on pages 13, 14, 15	5, and 16)
 10. Type of Regulated Waste Activity (Mark 'X' in the appropriate both A. Hazardous Waste Activities 1. Generator of Hazardous Waste (choose only one of the following three categories) ∑ a. LQG: Greater than 1,000 kg/mo (2,200 lbs.) of non-acute hazardous waste; or □ b. SQG: 100 to 1,000 kg/mo (220 - 2,200 lbs.) of non-acute hazardous waste; or □ c. CESQG: Less than 100 kg/mo of non-acute hazardous waste In addition, indicate other generator activities (check all that apply) □ d. United States Importer of Hazardous Waste □ e. Mixed Waste (hazardous and radioactive) Generator 					For Item	s 2 through 6, Transporter Treater, Stor your site) No for this activity Recycler of I hazardous wa Exempt Boile a. Small b. Smelti	check all that apply: of Hazardous Waste er, or Disposer of Haz ote: A hazardous waste	ardous Waste (at permit is required rour site) Note: A ired for this activity. urnace r Exemption
1. Large Quantity Handler of Universal Waste [refer to your State regulations to determine what is regulated]. Indicate types of universal waste generated and/or accumulated at your site. (check all boxes that apply): Generated Accumulated				vaste that apply): ccumulated	2. Us of	a. Transport b. Transfer F sed Oil Proces Activity(ies) a. Processor b. Re-refiner f-Specification sed Oil Fuel M ctivity(ies) a. Marketer V Used Oil I	Facility sor and/or Re-refiner	- Indicate Type(s) e(s) of of Off-Specification d Oil Burner
44			be required for this activ			Specificat	ions	
_	Waste Codes fo	r Federally Regulated	l Hazardous Wastes. P Julations (e.g., D001, D0	lease list the wast				t your site. List them
	D001	D008	D021	D033		D040	F004	
	D002	D009	D022	D034		D041	F005	

F003 D007 D019 D032 D039 Nota 750 per David Green@ MONR.

D027

D028

D029

D030

U122

U147

U228

D035

D036

D037

D038

D042 D043

F001

F002

D010

D011

D015

D018

D003

D004

D005

D006

				EPA ID No.	
B. Waste Codes for State-Regulated (i.e., at your site. List them in the order they are	non-Federal) Hazard	lous Wastes. Please listions. Use an addition	st the waste codes of the	e State-regulated hazard are needed for waste co	lous wastes handled des.
	, p				
D098					
					· · · · · · · · · · · · · · · · · · ·
					<u></u>
12. Comments (see instructions on page	17)			l	
Other less commonly ge	nerated was	ste codes aı	re as ident:	ified in our	
"Notification Of Regul					
Missouri Department Of					
information is needed.					
	**				
13. Certification. I certify under penalty of la	aw that this document	and all attachments we	e prepared under my d	irection or supervision in	accordance with a
system designed to assure that qualified pers manage the system, or those persons directly	responsible for gather	ring the information, the	information submitted i	s, to the best of my know	vledge and belief,
true, accurate, and complete. I am aware that for knowing violations. (see instructions on	there are significant popage 17)	enalties for submitting f	alse information, includ	ing the possibility of fine	and imprisonment
Signature of owner, operator, or an authorized representative		Name and Official	Title (type or print)		Date Signed (mm-dd-yyyy)
Mr. Clivitor	Robin K. F	rokop			03/01/02
·					

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:							
SITE NAME: Solutia Inc.,							
	John F. Queeny Plant						
EPA ID NO: MOD Q04 954 111							

2001 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

this for	this form. In addition, the page number for instructions specific to each box is provided in parentheses.							
Sec. 1	Sec. 1 A. Waste description (page 22) Ignitable spent solvent from laboratory; Acetone & Methanol							
B. EPA ha)22]	C. State hazard	ous waste code (page	22)			
D. Source (page :	23) Management Method code for Source code G25	Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generate	od in 2001 (page 23)	H. UOM (page 23) Density Ibs/gal sg		
Sec. 2	Sec. 2 Was any of this waste managed on site? (page 24) 1 Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) X 2 No (SKIP TO SEC. 3)							
ON-SITE	PROCESS SYSTEM 1		ON-SITE PROC	ESS SYSTEM 2		_		
	On-site Management Quantity treated, disposed, or Method code (page 24) recycled on site in 2001 (page 25) H							
Sec. 3	A. Was any of this waste shipped off site in 1 Yes (CONTINUE TO BOX B)		nent, disposal, or r IS COMPLETE)	ecycling? (pages 25 a	nd 26)			
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-si Shipp	ite Management Moed to (page 26)	lethod code	D. Total quantity ship (page 26)	oped in 2001		
	TXD 055 141 378	」	H040		L	7,090].		
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Moed to (page 26)	lethod code	D. Total quantity ship (page 26)	oped in 2001		
		J	Н		L			
Site 3	B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Moed to (page 26)	lethod code	D. Total quantity ship (page 26)	oped in 2001		
			LH					
Commen	Comments:							

BEFORE COF OR ENTER:	PYING FORM, ATTACH SITE IDENTIFICATION LABEL	
SITE NAME:	Solutia Inc.,	
	John F. Queeny Plant	_
EPA ID NO:	MOD 004 954 111	

2001 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

this form. In addition, the page number for instructions specific to each box is provided in parentheses.								
Sec. 1	A. Waste description (page 22) Floor sweepings and l	ab samp	les, cont	aining Mal	eic Anhydric	le		
B. EPA h	azardous waste code U147	1	C. State hazard	ous waste code (page	22)			
(page :	22)		L					
D. Source	-	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generate	ed in 2001 (page 23)	H. UOM (page 23)		
	[H]	w 409	Yes	3	, 970]. [_]	 lbs/gal sg		
Sec. 2	Was any of this waste managed on site? (pa	ige 24)						
	1 Yes (CONTINUE TO ON-SITE PRO 2 No (SKIP TO SEC. 3)	CESS SYSTEM	Л 1)					
ON-SITE	PROCESS SYSTEM 1		ON-SITE PROC	ESS SYSTEM 2				
	Quantity treated, dispose recycled on site in 2001 (On-site Manage Method code (pa		tuantity treated, disposed ecycled on site in 2001 (p			
[H			[H]		L			
Sec. 3	A. Was any of this waste shipped off site in 1 Yes (CONTINUE TO BOX B)		ent, disposal, or r S COMPLETE)	ecycling? (pages 25 a	nd 26)			
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26)		te Management M ed to (page 26)	lethod code	D. Total quantity shipp (page 26)	ed in 2001		
	TXD 055 141 378	」	[H040]			3,810].		
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)		te Management Med to (page 26)	lethod code	D. Total quantity shipp (page 26)	ed in 2001		
			Н					
Site 3	 B. EPA ID No. of facility to which waste was shipped (page 26) 		te Management Med to (page 26)	lethod code	D. Total quantity shipp (page 26)	ed in 2001		
	[H] [H] [L] [L] [L] [L] [L] [L] [L] [L] [L] [L							
Commen	Comments: Section 1; Box E: Maleic Anhydride Solid							

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:							
SITE NAME:	Solutia Inc.						
	John F. Queeny Plant						
EPA ID NO:	MOD 004 954 111						

2001 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.								
Sec. 1 A. Waste description (page 22) Hydraulic Fluids; Hazardous for barium, cadmium and benzene								
B. EPA h	azardous waste code	<u>6</u>	C. State hazard	ous waste code (page	22)			
D. Source (page	23) Management Method code for Source code G25	orm code page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generate	d in 2001 (page 23)	H. UOM (page 23) Density Ibs/gal gg		
Sec. 2	Was any of this waste managed on site? (page 1 Yes (CONTINUE TO ON-SITE PROCE 2 No (SKIP TO SEC. 3)		M 1)					
	PROCESS SYSTEM 1			ESS SYSTEM 2				
	lanagement Quantity treated, disposed, o ode (page 24) recycled on site in 2001 (pag		On-site Manager Method code (pa		uantity treated, disposed, cycled on site in 2001 (p			
Н		<u> </u>	[H					
Sec. 3	A. Was any of this waste shipped off site in 200 1 Yes (CONTINUE TO BOX B) 2 I		nent, disposal, or r S COMPLETE)	ecycling? (pages 25 ar	nd 26)			
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26)		te Management M ed to (page 26)	ethod code	D. Total quantity shippe (page 26)	ed in 2001		
/	[KYD][053][348][108]	-	[H050]		8	3,181		
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)	1	ite Management Moded to (page 26)	ethod code	D. Total quantity shippe (page 26)	ed in 2001		
	[TXD] 055 141 378		H040		1	8,834].		
Site 3	B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management M ped to (page 26)	ethod code	D. Total quantity shippe (page 26)			
Comments: Section 1; Box D: Draining of process lines Section 1; Box E: Hydraulic Fluid Liquid								

Over >

BEFORE COF OR ENTER:	YING FORM, ATTACH SITE IDENTIFICATION LABEL
SITE NAME:	Solutia Inc.
	John F. Queeny Plant
EPA ID NO:	MOD 004 954 111

2001 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

this for	this form. In addition, the page number for instructions specific to each box is provided in parentneses.								
Sec. 1	Sec. 1 A. Waste description (page 22) Ignitable Aerosol Cans								
B. EPA h	azardous waste code D001		C. State hazard	ous waste code (pag	e 22)				
(page	22)		<u> </u>						
D. Source (page :	23) Management Method code for Source code G25	orm code age 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generat	ated in 2001 (page 23)	H. UOM (page 23) Density Ibs/gal sg			
Sec. 2	Was any of this waste managed on site? (page 2	4)							
Sec. 2	1 Yes (CONTINUE TO ON-SITE PROCES 2 No (SKIP TO SEC. 3)		M 1)						
ON-SITE	ON-SITE PROCESS SYSTEM 1 ON-SITE PROCESS SYSTEM 2								
	On-site Management Quantity treated, disposed, or Method code (page 24) recycled on site in 2001 (page 25) On-site Management Quantity treated, disposed, or Method code (page 24) recycled on site in 2001 (page 25)								
LH_		<u> </u>	[H						
Sec. 3	A. Was any of this waste shipped off site in 200 1 Yes (CONTINUE TO BOX B) 2 N		nent, disposal, or r IS COMPLETE)	ecycling? (pages 25	and 26)				
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-s Shipp	ite Management Moed to (page 26)	lethod code	D. Total quantity shippe (page 26)	ed in 2001			
X = 1	[TXD] 055 141 378		H040		<u> </u>	250].			
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Moed to (page 26)	lethod code	D. Total quantity shipp (page 26)	ed in 2001			
			Н						
Site 3	Site 3 B. EPA ID No. of facility to which waste was shipped (page 26) C. Off-site Management Method code Shipped to (page 26) D. Total quantity shipped in 2001 (page 26)					ed in 2001			
Comments: Section 1; Box D: Empty Aerosol Cans from maintenance operations Section 1; Box E: Aerosol Cans Solid									

Over >

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:						
SITE NAME:	Solutia Inc.					
	John F. Queeny Plant					
EPA ID NO: [MOD] 004] 954] 111]						

2001 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

	m. m addition, the page number for		•		·			
Sec. 1 A. Waste description (page 22) Fluorescent Light Bulbs; Characteristically hazardous for mercury								
	Fluorescent Light Bulk	s; Cha	racterist	cically	hazardous for me	rcury		
B. EPA h	azardous waste code D009		C. State hazard	ous waste code	e (page 22)			
(page 2	22)		L					
D. Source		Form code (page 23)	F. RCRA radioactive mixed	G. Quantity g	enerated in 2001 (page 23)	H. UOM (page 23)		
	[Н]	w 319 J	(page 23)		190].	sg		
Sec. 2	Was any of this waste managed on site? (pag	e 24)						
	1 Yes (CONTINUE TO ON-SITE PROC 2 No (SKIP TO SEC. 3)		M 1)					
ON-SITE	PROCESS SYSTEM 1		ON-SITE PROC	ESS SYSTEM	2			
	lanagement Quantity treated, disposed recycled on site in 2001 (p		On-site Manage Method code (pa		Quantity treated, disposed, o recycled on site in 2001 (pag			
Sec. 3	Sec. 3 A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? (pages 25 and 26) 1 Yes (CONTINUE TO BOX B) 2 No (FORM IS COMPLETE)							
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Noted to (page 26)	lethod code	D. Total quantity shipped (page 26)	in 2001		
	MNO 000 903 468	J	[H010]			150].		
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Noed to (page 26)	lethod code	D. Total quantity shipped (page 26)	in 2001		
	FLD 000 207 449	J	H010			401.		
Site 3	B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Noed to (page 26)	Method code	D. Total quantity shipped (page 26)	in 2001		
			Н					
Comments: Section 1; Box D: Changing out light bulbs Section 1; Box E: Fluorescent Light Bulbs Solid Section 3; Box C: Mercury is recovered from the bulbs								

Over 1

BEFORE COF OR ENTER:	PYING FORM, ATTACH SITE IDENTIFICATION LABEL
SITE NAME:	Solutia Inc.
	John F. Queeny Plant
EPA ID NO:	MOD 004 954 111

2001 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

this form. In addition, the page number for instructions specific to each box is provided in parentheses.							
Sec. 1 A. Waste description (page 22) Ignitable solvent in glass vials from lab with acetone: G.C. Vials							
B. EPA hazardous waste code D001 F003 C. State hazardous waste code (page 22)							
(page 22)							
	rm code age 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generate	ed in 2001 (page 23)	H. UOM (page 23) Density		
[н]	203	Yes		165].	lbs/gal sg		
Sec. 2 Was any of this waste managed on site? (page 2 1 Yes (CONTINUE TO ON-SITE PROCES 2 No (SKIP TO SEC. 3)		M 1)					
ON-SITE PROCESS SYSTEM 1		ON-SITE PROC	ESS SYSTEM 2				
On-site Management Quantity treated, disposed, or Method code (page 24) recycled on site in 2001 (page 25) On-site Management Quantity treated, disposed, or Method code (page 24) recycled on site in 2001 (page 25)					25)		
<u> </u>	<u> </u>	Н					
Sec. 3 A. Was any of this waste shipped off site in 200 1 Yes (CONTINUE TO BOX B) 2 N	1 for treatm o (FORM I	nent, disposal, or r IS COMPLETE)	ecycling? (pages 25 a	<u> </u>			
Site 1 B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Noed to (page 26)	lethod code	D. Total quantity shipped i (page 26)			
TXD 055 141 378		H040			165		
Site 2 B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Noed to (page 26)	lethod code	D. Total quantity shipped i (page 26)	n 2001		
		Н					
Site 3 B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Noed to (page 26)	lethod code	D. Total quantity shipped i (page 26)	n 2001		
		[Н					
Comments:							

Over

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:					
SITE NAME:	Solutia Inc.				
	John F. Queeny Plant				
EPA ID NO: [MOD 004 954 111				

2001 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

this form. In addition, the page number for instructions specific to each box is provided in parentheses.								
Sec. 1 A. Waste description (page 22) Ignitable Waste Liquid containing Heptane								
B. EPA h	B. EPA hazardous waste code D001			ous waste code (page	: 22)			
(page 2	22)		L					
D. Source	23) Management Method code for (p Source code G25	orm code age 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generate	ed in 2001 (page 23)	H. UOM (page 23) Density Ibs/gal Sg		
Sec. 2								
ON-SITE	PROCESS SYSTEM 1		ON-SITE PROC	ESS SYSTEM 2				
	On-site Management Quantity treated, disposed, or Method code (page 24) Consider Method code (page 24) Consider Method code (page 24) Consider Management Quantity treated, disposed, or Method code (page 24) Consider Management Method code (page 25) Consider Management Method code (page 26) Consider Management Method code (page 26) Consider Method code							
Sec. 3	A. Was any of this waste shipped off site in 200 1 Yes (CONTINUE TO BOX B) 2 N		nent, disposal, or r IS COMPLETE)	ecycling? (pages 25 a	nd 26)			
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26)	1	ite Management M bed to (page 26)	lethod code	D. Total quantity shipped (page 26)	d in 2001		
	TXD 055 141 378		H040			<u>565</u>].		
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Moed to (page 26)	lethod code	D. Total quantity shipped (page 26)	d in 2001		
			Н			⊔		
Site 3	B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Moed to (page 26)	lethod code	D. Total quantity shipped (page 26)	d in 2001		
			Н					
Comments: Section 1; Box D: Cleanout of process line (maintenance)								

Over >

	·
BEFORE COP OR ENTER:	YING FORM, ATTACH SITE IDENTIFICATION LABEL
SITE NAME:	Solutia Inc.,
	John F. Queeny Plant
EPA ID NO:	MOD 004 954 111

2001 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing

this form. In addition, the page number for instructions specific to each box is provided in parentheses.							
Sec. 1 A. Waste description (page 22) Ignitable Waste Liquid containing Methanol; Duralink process							
B. EPA hazardous waste code D001 F003 C. State hazardous waste code (page 22)					22)		
		Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generate		H. UOM (page 23) Density	
	[Н]	<u>v 203</u> j	Yes		230].	☐ lbs/gal ☐ sg	
Sec. 2	Sec. 2 Was any of this waste managed on site? (page 24) 1 Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) 2 No (SKIP TO SEC. 3)						
ON-SITE	PROCESS SYSTEM 1		ON-SITE PROC	ESS SYSTEM 2			
	lanagement Quantity treated, disposed, pde (page 24) recycled on site in 2001 (page 24)		On-site Manage Method code (pa		uantity treated, disposed, or ecycled on site in 2001 (page		
[H		<u></u>	[H]				
Sec. 3	A. Was any of this waste shipped off site in 20 1 Yes (CONTINUE TO BOX B) 2		nent, disposal, or r S COMPLETE)	ecycling? (pages 25 ar	nd 26)		
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26)		ite Management Noed to (page 26)	lethod code	D. Total quantity shipped (page 26)	in 2001	
	TXD 0500 141 378		H040			230].	
Site 2			f-site Management Method code ipped to (page 26)		D. Total quantity shipped in 2001 (page 26)		
			Н		L		
Site 3			site Management Method code ped to (page 26)		D. Total quantity shipped (page 26)	in 2001	
			Н		<u> </u>		
Comments: Section 1; Box D: Quality Control samples from Duralink process							